



The World's Largest Range of PU Spray Tips!



AIRLESS SPRAY TIPS (260 Available) STUDWALL SPRAY TIPS (Only 2)

Control Output & Fan Width of PU Foam, Elastomer & Polyurea

Accurately Fine Tune Gun Output and Fan Pattern



Engineer's Mobile Spray Tip Box



Glascraft P2 Gun

LPA2-147-XXYY Tips - XX = Output (.0XX”) & YY = Fan Width (Angle)

0710		0720	0730	0740							
0910		0920	0930	0940	0950						
1110		1120	1130	1140	1150	1160	1170				
1310		1320	1330	1340	1350	1360	1370	1380			
1510		1520	1530	1540	1550	1560	1570	1580			
1710		1720	1730	1740	1750	1760	1770	1780	1790	17100	
1910		1920	1930	1940	1950	1960	1970	1980	1990	19100	
2110		2120	2130	2140	2150	2160	2170	2180	2190	21100	
		2320	2330	2340	2350	2360	2370	2380	2390	23100	23110
		2520	2530	2540	2550	2560	2570	2580	2590	25100	25110
		2720	2730	2740	2750	2760	2770	2780	2790	27100	27110
		2920	2930	2940	2950	2960	2970	2980	2990	29100	29110
3110	3115	3120	3130	3140	3150	3160	3170	3180	3190	31100	31110
3310	3315	3320	3330	3340	3350	3360	3370	3380	3390	33100	33110
3510	3515	3520	3530	3540	3550	3560	3570	3580	3590	35100	35110
3710	3715	3720	3730	3740	3750	3760	3770	3780	3790	37100	37110
3910	3915	3920	3930	3940	3950	3960	3970	3980	3990	39100	39110
		4120	4130	4140	4150	4160	4170	4180	4190	41100	41110
		4320	4330	4340	4350	4360	4370	4380	4390	43100	43110
		4520	4530	4540	4550	4560	4570	4580	4590	45100	45110
		4720	4730	4740	4750	4760	4770	4780	4790	47100	47110
		4920	4930	4940	4950	4960	4970	4980	4990	49100	49110
		5120	5130	5140	5150	5160	5170	5180	5190	51100	51110
		5320	5330	5340	5350	5360	5370	5380	5390	53100	53110
		5520	5530	5540	5550	5560	5570	5580	5590	55100	55110
		5720	5730	5740	5750	5760	5770	5780	5790	57100	57110
		5920	5930	5940	5950	5960	5970	5980	5990		
			6130	6140	6150	6160	6170	6180	6190		
			6330	6340	6350	6360	6370	6380	6390		
				7140	7150	7160	7170				

Glascraft UK Ltd

www.glascraft.co.uk

sales@glascraft.co.uk

Tel: +44 161 764 2977

